ANNEXURE 'A'

Certified that the building plans submitted for approval satisfy the safety requirements as stipulated under clause 18 of Building Bye-laws, 1983 and the information given therein is factually correct to the best of our knowledge and understanding.

 It is also certified that the structural design including safety from natural hazards based on soil conditions has been duly incorporated in the design of the building and these provisions had to be adhere during construction.

Signature of the store with date

MANSIR

GUFTA

BARYAGONT NOFLHILL

Name in Block letters

Address:

MUS HTAC

Prchosh JD Signature of Structural Engineer with date

(As defined in NBC of India)

Name in Block letters

ARCHITECT/// SHRI MUSHTAQ MEHMCOD CA/2008/41803

Smt.

5JB11951

Address: 1024 SHARIE

PRAKASH VERVA Structural Engineer M.C.D. License No. SE-02 B-2/2. Sec-18. Rohini Deihi Pn-27882422



Manager, Ø. Bhakti Mandir Premwati Public School